

FIELD ACTIVITY DAILY LOG

ROCKY FLATS PROJECT Ground Water Sampling Program | PROJECT NO 30490233 cv af

FIELD ACTIVITY SUBJECT Landfill Explosive Gas Monitoring

DESCRIPTION OF DAILY ACTIVITIES AND EVENTS

- 1230 - Calibrate MSA Minigard III
1300 - Leave base - pick up buffer zone pass for JMT.
1315 - Arrive at Landfill - set up LFL and HAN - Background check for HAN
1325 - Arrive at Well 44592 - take readings (LFL + HAN)
1330 - Arrive at Well 44492 - take readings
1335 - Arrive at Well 44692 - take readings
1340 - Arrive at Well 44292 - take readings
1345 - Arrive at Well 44392 - take readings
1350 - Arrive at perimeter point #4 - take readings
1353 - Arrive at perimeter point #5 - take readings
1355 - Arrive at perimeter point #6 - take readings
1358 - Arrive at perimeter point #1 - take readings
1400 - Arrive at perimeter point #2 - take readings
1402 - Arrive at perimeter point #3 - take readings
1405 - Leave Landfill to return to base
1420 - Drop off buffer pass for JMT
1430 - Post Calibration for MSA Minigard III
1440 - Fill out logs
1450 - Complete all logs
1500 - End of task

VISITORS ON SITE.

CHANGES FROM PLANS AND SPECIFICATIONS, AND OTHER SPECIAL ORDERS AND IMPORTANT DECISIONS.

WEATHER CONDITIONS. (precip., temp., clouds)

IMPORTANT TELEPHONE CALLS.

SAMPLING TEAM PERSONNEL

SIGNATURE OF PREPARED

DATE 9/18/92